

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

RECEIVED

JAN 24 1994

ANNUAL REPORT OF MINING OPERATIONS

DIVISION OF
OIL, GAS & MINING

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan. 93 To (mo./yr.) Dec. 93
 2. DOGM File Number (Mine No): S/001/008
 3. Mine Name: VKGK (Vicksburg, Kopect, Gold King Groups) (Patented)
 4. Mineral(s) Mined (or permitted to mine): Precious Metals, Base Metals, Marble, Serpentine, Wundersite
 5. Type of mine ☒ Surface Mine and ☒ Underground Mine
 6. Legal Description (Location of Lands Affected):
NW 1/4, SE 1/4, Section 21, Township 28 S, Range 11 W
NE, NW 1/4, NW 1/4, Section 28, Township 28 S, Range 11 W
NE, NW, SE 1/4, NE 1/4, Section 29, Township 28 S, Range 11 W
NE 1/4, SW 1/4, Section 29, Township 28 S, Range 11 W
 7. Name of Operator or Company: Byron & Cecil Muir - Star Mountain Gold
 8. Permanent Street Address: P.O. Box 766 4489 S. Hwy 129
City, State, Zip: Milford, Utah 84751
Phone: (801) 387-2351
 9. Company Representative (or designated operator):
Name: Same as Above
Title: _____
Business Address: _____
City, State, Zip: _____
Phone: _____
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 85 TONS Mined

940001 And Sorted.

3. How much **additional acreage** was disturbed during the past year? 0

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Work was on existing disturbances
only. Road Repair and Maintenance
was performed on existing roads.

5. How much acreage was **reclaimed** during the past year? 0.05 Acre

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

All Reclamation was Natural
in affected areas from last year.

7. What is the **total disturbed acreage** at years end? 0

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Continued Mining and Road
Maintenance throughout property. Also
Facility Construction will be continuing.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Cecil H Muir

Title of Operator:

Project Manager (owner)

Signature of Operator:

Cecil H Muir

Date:

1-11-94